

PRODUCT OBSOLESCENCE MEMO SENSORS AND CONTROLS



Bourns® Model PDB184 Potentiometer with Rotary Switch to be Discontinued

Riverside, California – April 14, 2020 – Effective immediately, in accordance with our ongoing product lifecycle management procedure, Bourns is transferring the Model PDB184 Potentiometer with Rotary Switch to an End of Product Life status. Obsolescence of the tooling used to fabricate this series by the supplier and a lack of sales volume and diminishing demand necessitates this action.

| Obsolete Part Numbers | |
|-----------------------|--------------------|
| PDB184-K420K-103A1 | PDB184-K425K-503A1 |
| PDB184-K420K-254A1 | PDB184-K425K-503B1 |
| PDB184-K420K-503B1 | PDB184-K430K-103B1 |
| PDB184-K425K-103B | PDB184-S420K-103B1 |
| PDB184-K425K-103B1 | PDB184-S425K-103A1 |

Regrettably, no replacement product is available at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued product. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for this model will be considered non-cancellable and non-returnable.

Should you have any questions or need additional information, please feel free to contact <u>Customer Service/Inside</u> Sales.

SC2027